



# City of Saint Louis

## DEPARTMENT OF HEALTH & HOSPITALS DIVISION OF HEALTH

FMD 579 PA  
10-2-45

VINCENT C. SCHOEMEHL, Jr.  
Mayor

Dian Sharma, Ph. D.  
Health Commissioner

April 21, 1987

Mound Street  
M00000093682  
1.1

TO: Lee Huguley  
Assistant Manager

FROM: Daniel J. Wilson *DJW*  
Environmental Sanitation Specialist

SUBJECT: Sampling effort at Number 2 Mound Street/  
1725 North L.K. Sullivan

4.21.87

Upon receiving your approval, Linda Harris, Environmental Sanitation Specialist, and I visited Number 2 Mound Street/ 1725 North L. K. Sullivan on April 8, 1987, for the purpose of sampling the oil accumulation at same. During the time spent at the location, we were not able to sample all suspected locations. This effort was curtailed due to only being able to remove one manhole cover because our divisions cover puller was not designed to remove the other lids.

To conclude this portion of our divisions involvement with the site, I gave the six samples we did obtain to Dr. Jonsson of our Public Health Laboratory on April 8, 1987, at approximately 3:00 pm. When this was accomplished he agreed to analyse them for PCB content. I have attached the sampling datum to this memorandum. It should be noted that these sample results are only indicators and they do not confirm or deny the lack of PCBs in the samples taken.

My next step in this investigation will be to meet with Union Electric personnel once they have found information which may pertain to the actual storage of oil at the site. Therefore, unless otherwise directed, this inquiry into the oil contamination at the former Mound Street Power Company is on hold.

cc: Thomas Astorino  
Deputy Assistant Health Commissioner

File ✓

DJW:bmc

30017117



Superfund

MOUND STREET POWER COMPANY  
#2 Mound Street/1725 North L. K. Sullivan

Date Sampled -----	Time Sampled -----	Sample Number -----	Sample Location -----	PCB Level PPM -----
April 8, 1987	10:45 a.m.	I	East basement sump pump	0.00
April 8, 1987	10:00 a.m.	II	North basement	0.00
April 8, 1987	11:15 a.m.	III	Bucket at east basement sump pump	0.00
April 8, 1987	11:30 a.m.	IV	South building basement	0.00
April 8, 1987	11:45 a.m.	V	East side of south building basement	0.00
April 8, 1987	12:30 p.m.	VI	Mound street water meter box, northwest exterior corner of building	0.00

Note: While peaks appeared on the samples ran, no peaks  
were seen that corresponded with the laboratory  
PCB standards.